

PACKING INSTRUCTIONS

U-BAR

STEP 1

TOP PANEL 115X74
5 x CE-0008

Place the top surface against each other



STEP 2

BAR TOP METAL 115X22
6 x CE-0116



STEP 3

BAR PANEL LONG 115X105
5 x CE-0130

Place the visible sides against each other to prevent damage



STEP 4

Place cardboard



STEP 5

BAR PANEL SHORT 80X105
4 x CE-0131

Place the visible sides against each other to prevent damage



STEP 6

Place cardboard



STEP 7

BAR SUPPORT FRAME 115X90
5 x CE-0148



STEP 8

CONNECTOR STRAIGHT
115X105
4 x CE-0146



STEP 9

CORNER CONNECTOR RIGHT
115X105
1x CE-0132



STEP 10

CORNER CONNECTOR LEFT
115X105
1x CE-0133



STEP 11

Strap the items
and close the bottom of the box



STEP 12

Close the top of the box

